

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2551	DATE	Oct. 20, 2017
MANUFACTURER	Bentley Motors Limited (Japanese Importer : Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to incorrect program of the meter panel control unit which controls the seat belt alert when seat belt is unfastened, the seat belt alert does not go off correctly when driving with seat belt unfastened in accordance with the technical requirements of the regulation No.16. Therefore it does not exactly meet the article 22, paragraph 3 of the safety regulation of the Road Vehicle Act.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-BBCZM	Mulsanne	2017	9