

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4137	DATE	Nov. 16, 2017
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	At the final vehicle inspection process in the vehicle assembly plants, there were cases that the inspectors conducted the final vehicle inspection prior to promotion as the final vehicle inspector. Therefore, inspections related to the Japanese safety standard might have been conducted inappropriately.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
DBA-VM4	「LEVORG」	2014-2017	Approx.62,000	
DBA-VMG		2014-2017	Approx. 14,000	
DBA-VAG	「WRX」	2014-2017	Approx. 14,000	
CBA-VAB		2014-2017	Approx.9,000	
DBA-GJ2	「IMPREZA」	2014-2016	Approx.2,000	
DBA-GJ3		2014-2016	Approx. 4,000	
DBA-GJ6		2014-2016	Approx.500	
DBA-GJ7		2014-2016	Approx.4,000	
DBA-GK2		2016-2017	Approx. 1,000	
DBA-GK3		2016-2017	Approx. 1,000	
DBA-GK6		2016-2017	Approx.3,000	
DBA-GK7		2016-2017	Approx.5,000	
DBA-GP2		2014-2016	Approx.8,000	
DBA-GP3		2014-2016	Approx. 14,000	
DBA-GP6		2014-2016	Approx. 1,400	
DBA-GP7		2014-2017	Approx.42,000	
DAA-GPE		2014-2017	Approx. 10,000	
CBA-GRF		2014	1	
DBA-GT2		2016-2017	Approx.8,000	
DBA-GT3		2016-2017	Approx.5,000	
DBA-GT6		2016-2017	Approx.9,000	
DBA-GT7		2016-2017	Approx. 15,000	
DBA-GT3		「XV」	2017	Approx.4,000
DBA-GT7			2017	Approx. 15,000
DBA-SJ5	「FORESTER」	2014-2017	Approx.57,000	
DBA-SJG		2014-2017	Approx. 12,000	

DBA-BM9	「LEGACY」	2014	Approx.200
DBA-BMG		2014	Approx.10
DBA-BMM		2014	Approx.10
DBA-BN9		2014-2017	Approx.9,000
DBA-BRF		2014	1
DBA-BRG		2014	Approx.10
DBA-BRM		2014	Approx.80
DBA-BS9		2014-2017	Approx.28,000
DBA-YA5		「EXIGA」	2014-2015
DBA-YAM	2014-2017		Approx.12,000
DBA-ZC6	「BRZ」	2014-2017	Approx.6,000
DBA-ZN6	「86」	2014-2017	Approx.19,000
		TOTAL	Approx.395,000