

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai- 2569	Date	Nov. 29, 2017
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)		
Description of defect	<p>A concern has been identified with certain Jaguar XJ 2010 and 2011 Model Year (MY) vehicles where, when connected to Jaguar Land Rover's Symptom Driven Diagnostics (SDD) device and an update to the Restraint Control Module (RCM) is unsuccessfully undertaken, the calibration may default to a pre-set condition.</p> <p>In the event of a frontal impact of a sufficient severity to require the Supplementary Restraint System (SRS) to deploy the front airbags, the airbags will deploy but at impact thresholds that exceed those which provide the required occupant protection. Failure of the airbags to deploy as required can lead to increased injuries to the occupants.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
CBA-J12LA	「XJ Lux. 」 「XJ Prem. Lux.」	2010-2011	506
CBA-J24MA	「XJ Supersport LWB」	2010-2011	34
CBA-J12MA	「XJ Supersport」	2010-2011	14
Total			554