

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai – 2570	Date	Nov. 29, 2017
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)		
Description of defect	<p>A concern has been identified on certain Land Discovery 4 2012 and 2013 Model Year vehicles where the panoramic roof adhesive and primer used in the assembly bonding of the panoramic roof glass panel may not have been to the correct specification.</p> <p>Jaguar Land Rover's continuous review of warranty reports identified a concern where the customer reported wind noise during driving and when parked, on closing a vehicle door the panoramic roof glass was seen to lift. A further report was identified where the panoramic roof glass detached from the vehicle while the vehicle was in motion.</p> <p>Where the panoramic roof glass panel detaches from the vehicle during normal road driving, it may collide with other vehicles on the road or compel other road users to take evasive action. This could increase the risk of a vehicle crash.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
ABA-LA5N	「Discovery 4」	2012	8
Total			8