

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic)/ Import Vehicles

CAMPAIGN No.	4397	DATE	Dec. 13. 2018
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain E13C type engines for heavy duty trucks, because the dimension of the rocker part for intake valves is inadequate, the valve may tilt, causing the partial wear of intake valve guides. This may cause repeated parts contact noise and vibration, resulting the engine to stop if it is continued to be used under the condition.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-FN1EWAG	[HINO Profia]	2010～2014	156
LKG-FN1EWAG			
QKG-FN1EWAA			
QKG-FN1EWAG			
LDG-FN1EWBA		2010～2013	13
QDG-FN1EWBA			
QKG-FN1EWDG		2014～2017	176
QDG-FN1EWEA		2014～2016	5
ADG-FN1EWXA		2006～2010	332
ADG-FN1EWXG			
BDG-FN1EWXA			
BDG-FN1EWXG			
ADG-FN1EWYA		2006～2010	30
BDG-FN1EWYA			
LDG-FN1EYBG		2010～2014	99
LKG-FN1EYBG			
QKG-FN1EYBG			
ADG-FN1EYYA		2006～2010	118
ADG-FN1EYYG			
BDG-FN1EYYA			
BDG-FN1EYYG			
ADG-FQ1ERYA		2006～2010	137
BDG-FQ1ERYA			
ADG-FQ1ETYA		2006～2010	43
BDG-FQ1ETYA			
LDG-FQ1EWBG		2010～2014	572
LDG-FQ1EWBJ			
LKG-FQ1EWBG			
LKG-FQ1EWBJ			
QKG-FQ1EWBG			
QKG-FQ1EWBJ			
QPG-FQ1EWEG		2014～2017	580
QPG-FQ1EWEJ			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-FQ1EWYG ADG-FQ1EWYJ BDG-FQ1EWYA BDG-FQ1EWYG BDG-FQ1EWYJ	[HINO Profia]	2006～2010	443
LDG-FR1EPBA LKG-FR1EPBA QDG-FR1EPBA QKG-FR1EPBA		2010～2014	220
QKG-FR1EPEA QPG-FR1EPEA		2014～2017	252
ADG-FR1EPYA BDG-FR1EPYA		2005～2010	526
ADG-FR1ESYA BDG-FR1ESYA		2006～2010	106
LDG-FR1EUBA LKG-FR1EUBA QDG-FR1EUBA QKG-FR1EUBA		2010～2014	30
QKG-FR1EUEA QPG-FR1EUEA		2015～2017	18
ADG-FR1EUYA BDG-FR1EUYA		2006～2010	69
ADG-FR1EVXA BDG-FR1EVXA		2006～2010	9
ADG-FR1EWXA BDG-FR1EWXA		2006～2009	21
LDG-FR1EXBA LDG-FR1EXBG LDG-FR1EXBJ LKG-FR1EXBA LKG-FR1EXBG LKG-FR1EXBJ QKG-FR1EXBA QKG-FR1EXBG QKG-FR1EXBJ		2010～2014	5, 131
QKG-FR1EXEG QKG-FR1EXEJ QPG-FR1EXEA QPG-FR1EXEG QPG-FR1EXEJ		2014～2017	6, 557

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-FR1EXYA ADG-FR1EXYG ADG-FR1EXYJ BDG-FR1EXYA BDG-FR1EXYG BDG-FR1EXYJ BKG-FR1EXYG BKG-FR1EXYJ	[HINO Profia]	2005～2010	6,995
LDG-FR1EZBG LDG-FR1EZZJ LKG-FR1EZBG LKG-FR1EZZJ QKG-FR1EZBG QKG-FR1EZZJ		2010～2014	720
QPG-FR1EZEG QPG-FR1EZEJ		2014～2017	453
ADG-FR1EZYG ADG-FR1EZYJ BDG-FR1EZYG BDG-FR1EZYJ BKG-FR1EZYG BKG-FR1EZYJ		2006～2010	1,888
LDG-FS1EKAA LKG-FS1EKAA QKG-FS1EKAA		2010～2014	3,389
QKG-FS1EKDA		2014～2017	4,340
ADG-FS1EKXA BDG-FS1EKXA		2006～2010	2,301
ADG-FS1EMXA BDG-FS1EMXA		2006～2009	11
LDG-FS1EPBA LKG-FS1EPBA QKG-FS1EPBA		2010～2014	610
QKG-FS1EPEA QPG-FS1EPEA		2014～2017	616
ADG-FS1EPYA BDG-FS1EPYA		2006～2010	676
LDG-FS1ERBA LKG-FS1ERBA QDG-FS1ERBA QKG-FS1ERBA		2010～2014	489
QDG-FS1EREA QKG-FS1EREA QPG-FS1EREA		2014～2017	518
ADG-FS1ERXA		2006～2007	5

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-FS1ERYA	[HINO Profia]	2006～2010	619
BDG-FS1ERYA		2006～2010	67
ADG-FS1ETYA	[HINO Profia]	2010～2014	21
BDG-FS1ETYA		2014～2016	16
LDG-FS1EUBA		2006～2010	41
LKG-FS1EUBA		2010～2014	883
QDG-FS1EUBA	[HINO Profia]	2014～2017	1, 233
QPG-FS1EUEA		2006～2010	1, 106
QKG-FS1EUEA		2010～2014	211
QKG-FS1EWBA		2014～2017	146
QKG-FS1EWBG			
QKG-FS1EWBJ			
QKG-FS1EWYJ			
QPG-FS1EWBA	[HINO Profia]	2006～2010	619
QPG-FS1EWBG		2010～2014	21
QPG-FS1EWEA		2014～2016	16
QPG-FS1EWEA		2014～2017	1, 233
QPG-FS1EWEJ			
QPG-FS1EWYJ	[HINO Profia]	2006～2010	41
BKG-FS1EWYJ		2010～2014	211
BKG-FS1EWYG		2014～2017	146
ADG-FS1EWYA			
ADG-FS1EWYG	[HINO Profia]		
ADG-FS1EWYJ			
BDG-FS1EWYA			
BDG-FS1EWYG			
BDG-FS1EWYJ	[HINO Profia]		
BKG-FS1EWYG			
LDG-FS1EZBA			
LDG-FS1EZBG			
LKG-FS1EZBA	[HINO Profia]		
LKG-FS1EZBG			
QKG-FS1EZBA			
QKG-FS1EZBG			
QKG-FS1EZBJ	[HINO Profia]		
QPG-FS1ESEA			
QPG-FS1EZEG			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-FS1EZYA ADG-FS1EZYG ADG-FS1EZYJ BDG-FS1EZYA BDG-FS1EZYG BDG-FS1EZYJ	[HINO Profia]	2006～2010	440
ADG-FW1EAXG BDG-FW1EAXG		2006～2010	26
LDG-FW1EBBG LDG-FW1EBBJ LKG-FW1EBBG LKG-FW1EBBJ QKG-FW1EBBG QKG-FW1EBBJ		2010～2014	144
QPG-FW1EBEG QPG-FW1EBEJ		2014～2017	77
ADG-FW1EBYG ADG-FW1EBYJ BDG-FW1EBYG BDG-FW1EBYJ BKG-FW1EBYG BKG-FW1EBYJ		2006～2010	114
ADG-FW1ETYA BDG-FW1ETYA		2006～2010	25
LDG-FW1EWBA LKG-FW1EWBA QKG-FW1EWBA		2010～2014	326
QKG-FW1EWEA QPG-FW1EWEA		2014～2017	435
ADG-FW1EWYA BDG-FW1EWYA		2006～2010	250
LDG-FW1EXAG QKG-FW1EXAG		2010～2012	3
LDG-FW1EXBG LDG-FW1EXBJ LKG-FW1EXBG LKG-FW1EXBJ QKG-FW1EXBG QKG-FW1EXBJ		2010～2014	6,968
QKG-FW1EXDG		2015～2016	6
QKG-FW1EXEG QKG-FW1EXEJ QPG-FW1EXEG QPG-FW1EXEJ		2014～2017	11,253
ADG-FW1EXXG BDG-FW1EXXG		2006～2010	83

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-FW1EXYG ADG-FW1EXYJ BDG-FW1EXYG BDG-FW1EXYJ BKG-FW1EXYG BKG-FW1EXYJ	[HINO Profia]	2005～2010	7, 124
LDG-FW1EYBG LDG-FW1EYBJ LKG-FW1EYBG LKG-FW1EYBJ QKG-FW1EYBG QKG-FW1EYBJ		2010～2014	214
LDG-FW1EYCG LKG-FW1EYCG QKG-FW1EYCG		2010～2013	14
QPG-FW1EYEG QPG-FW1EYEJ		2014～2017	250
ADG-FW1EYYG ADG-FW1EYYJ BDG-FW1EYYG BDG-FW1EYYJ BKG-FW1EYYG BKG-FW1EYYJ		2006～2010	346
ADG-FW1EYZG ADG-FW1EYZJ BDG-FW1EYZG BDG-FW1EYZJ		2006～2010	63
LDG-FW1EZBG LDG-FW1EZBJ LKG-FW1EZBG LKG-FW1EZBJ QKG-FW1EZBG QKG-FW1EZBJ		2010～2014	983
QKG-FW1EZEG QPG-FW1EZEG QPG-FW1EZEJ		2014～2017	1, 610
ADG-FW1EZXG BDG-FW1EZXG		2006～2010	136
ADG-FW1EZYG ADG-FW1EZYJ BDG-FW1EZYG BDG-FW1EZYJ BKG-FW1EZYG BKG-FW1EZYJ		2006～2010	1, 054

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-SH1EDAG LKG-SH1EDAJ QKG-SH1EDAG QKG-SH1EDAJ	[HINO Profia]	2010～2014	3,371
QPG-SH1EDDG QPG-SH1EDDJ		2014～2017	4,839
ADG-SH1EDXG ADG-SH1EDXJ BDG-SH1EDXG BDG-SH1EDXJ BKG-SH1EDXG BKG-SH1EDXJ		2006～2010	4,906
LKG-SH1EEAG QKG-SH1EEAG	[HINO Profia]	2010～2014	260
QPG-SH1EEDG		2014～2017	543
ADG-SH1EFXG BDG-SH1EFXG		2006～2010	180
LKG-SH1EGAG QKG-SH1EGAG QKG-SH1EGAJ	[HINO Profia]	2010～2014	613
QKG-SH1EGDG QPG-SH1EGDG		2014～2017	833
ADG-SH1EGXG ADG-SH1EGXJ BDG-SH1EGXG BKG-SH1EGXG BKG-SH1EGXJ		2006～2010	751
LDG-SS1EKAA LDG-SS1EKAG LKG-SS1EKAG QDG-SS1EKAA QDG-SS1EKAG QKG-SS1EKAG	[HINO Profia]	2010～2014	865
QDG-SS1EKDA QPG-SS1EKDA QPG-SS1EKDG		2014～2017	1,026
ADG-SS1EKXA BDG-SS1EKXA		2006～2010	858
		TOTAL	93,986