

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2864	DATE	Jun. 26, 2019
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>Brake master cylinder may not meet the specifications in individual cases. A brake system failure may result.</p> <p>The brake master cylinder on the affected vehicles must be checked and replaced if necessary.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-FYCWGS	Audi SQ5	2018	23
DBA-FYDAXA	Audi Q5 2.0Tq Air suspension	2018	24
DBA-FYDAXS	Audi Q5 2.0Tq	2018	203
		Total	250