

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4527	DATE	June 27,2019
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In certain the passenger's airbag inflators, gas generating propellant may get deteriorated through repetition of environmental temperature and humidity fluctuations. This can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator whereby the container of inflator could be broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
LA-GD1	「FIT」	2001～2003	98,383	
UA-GD1		2003	20,040	
DBA-GD1		2004～2007	62,987	
LA-GD2		2001～2003	14,011	
UA-GD2		2003	642	
DBA-GD2		2004～2007	8,244	
LA-GD3		2002～2003	17,217	
UA-GD3		2003	1,779	
CBA-GD3		2004～2005	7,738	
DBA-GD3		2005～2007	4,152	
LA-GD4		2002～2003	2,704	
UA-GD4		2003	276	
CBA-GD4		2004～2005	1,164	
DBA-GD4		2005～2007	606	
LA-RN1		「STREAM」	2000～2003	28,803
UA-RN1			2003	1,763
CBA-RN1	2004～2006		6,123	
LA-RN2	2000～2003		4,921	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-RN2	「STREAM」	2004～2006	932
LA-RN3		2000～2003	24,754
UA-RN3		2003	859
CBA-RN3		2004～2006	1,691
LA-RN4		2001～2003	5,762
ABA-RN4		2004～2006	749
UA-RN5		2003	647
CBA-RN5		2004～2006	1,338
LA-JD1		「THAT'S」	2002～2004
ABA-JD1	2004～2007		15,479
LA-JD2	2002～2004		3,608
ABA-JD2	2004～2007		2,741
LA-GB1	「MOBILIO」	2001～2003	17,627
UA-GB1		2003	3,122
CBA-GB1		2003～2005	2,468
DBA-GB1		2003～2008	10,421
LA-GB2		2001～2003	3,810
DBA-GB2		2003～2008	2,070
LA-GK1		「MOBILIO SPIKE」	2002～2004
CBA-GK1	2004～2005		6,852
DBA-GK1	2005～2008		7,877
LA-GK2	2002～2004		2,888
CBA-GK2	2004～2005		1,631
DBA-GK2	2005～2008		1,918
LA-CL7	「ACCORD」	2002～2004	1,796

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-CL7	「ACCORD」	2002～2004	4,102
ABA-CL7		2004～2008	2,667
CBA-CL7		2004	1,079
DBA-CL7		2004～2008	4,808
LA-CL8		2002～2004	617
ABA-CL8		2004～2008	823
LA-CL9		2002～2004	2,958
ABA-CL9		2004～2008	2,913
LA-RD4		「CR-V」	2001～2004
ABA-RD4	2004		375
LA-RD5	2001～2004		9,794
ABA-RD5	2004		740
CBA-RD6	2004～2006		1,306
CBA-RD7	2004～2006		4,344
LA-ES1	「CIVIC FERIO」		2000～2003
UA-ES1		2001～2004	966
CBA-ES1		2004～2005	344
LA-ES2		2000～2004	905
ABA-ES2		2004～2005	141
LA-ES3		2000～2003	1,118
UA-ES3		2003～2004	410
CBA-ES3		2004～2005	1,489
LA-ET2		2003～2004	48
ABA-ET2		2004～2005	236
DBA-CM1		「ACCORD WAGON」	2004～2007

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-CM2	「ACCORD WAGON」	2002～2004	2,146
UA-CM2			2,313
ABA-CM2		2004～2007	644
CBA-CM2		2004	276
DBA-CM2		2004～2007	623
LA-CM3		2002～2004	898
ABA-CM3		2004～2007	302
ZA-ES9		「CIVIC HYBRID」	2001～2004
CAA-ES9	2004～2005		180
		TOTAL	494,546

Applicable to passenger's airbag inflator shipped as a field servicing part so far as it is possible to trace the vehicle to which it may have been fitted.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-RR1	「ELYSION」 「ELYSION PRESTAGE」	2008～2012	3
DBA-RR2	「ELYSION PRESTAGE」	2008	1
DBA-RR3	「ELYSION」	2004～2005	4
DBA-RR4		2004	1
ABA-RB1	「ODYSSEY」	2007	1
DBA-RB1			1
DBA-CU1	「ACCORD」	2011	1
DBA-CU2		2008	1
DBA-CW2	「ACCORD TOURER」	2010	1
DBA-FD1	「CIVIC」	2005～2009	6
ABA-FD2		2007～2010	10

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-FD3	「CIVIC HYBRID」	2006～2009	3
DBA-KB1	「LEGEND」	2004～2006	2
DBA-KB2		2011～2012	2
DBA-RE3	「CR-V」	2006～2008	2
DBA-RE4			8
DBA-GE6	「FIT」	2007～2011	13
DBA-GE7		2007	2
DBA-GE8		2007～2011	5
DAA-GP1		2010	1
DBA-GG7		「FIT SHUTTLE」	2011
DBA-GB3	「FREED」	2008	1
DBA-GB4		2008	1
DAA-ZE2	「INSIGHT」	2009～2010	3
		TOTAL	74