

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2987	DATE	Feb. 20, 2020
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	Airbag may not deploy properly and lead to an increased risk of injury. The airbag module or its components will be replaced.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
E-4BACKF	Audi A6 2.4 quattro	1998 - 1999	134
E-4BAGA	Audi A6 2.4	1998 - 1999	222
E-4BAGAF	Audi A6 2.4 quattro	1998 - 1999	56
E-4DABZ	Audi A8 quattro 4.2	1998	16
E-8DABC	Audi A4 2.6	1997	21
E-8DACKF	Audi A4 2.8 quattro	1998 - 1999	57
E-8DADR	Audi A4 1.8	1997 - 1999	400
E-8DAEBF	Audi A4 1.8T quattro	1997 - 1999	126
E-8DAGA	Audi A4 2.4	1998 - 1999	356
E-8DAGAF	Audi A4 2.4 quattro	1998 - 1999	144
GF-4BAPRF	Audi A6 2.8 quattro	1999 - 2000	32
GF-4BAPSF	Audi A6 2.4 quattro	1999 - 2000	12
GF-4DAQF	Audi A8 quattro 4.2	2000	10
GF-8DADR	Audi A4 1.8	1999	2
GF-8DAGBF	Audi S4	1999 - 2000	49
GF-8DAPS	Audi A4 2.4	1999	1
GF-8DAPSF	Audi A4 2.4 quattro	1999 - 2000	73
GF-8DAPUF	Audi A4 1.8T quattro	1999	5
GF-8NAPXF	Audi TTCoupé 1.8T quattro / Audi TT Roadster 1.8T quattro	2000	174
		Total	1,890