

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2997	DATE	2020/3/10
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain G-Class vehicles (463 platform) the wiring harness for the front doors might not be routed appropriately.</p> <p>Individual cables could be damaged due to movement of the wiring harness when opening and closing the front doors.</p> <p>The potential safety consequence(s) depend on the cable that is affected, but could for example impact the performance of the side impact restraint system, the automatic unlocking of the door in case of a crash or the vehicle location in the event of an emergency call, all increasing the risk of injury in the event of a crash.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-463260	G550	2019	240
ABA-463276	Mercedes AMG G63		821
		TOTAL	1,061