

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-2999	DATE	Mar. 17, 2020
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : Groupe PSA Japan Co.,Ltd.)		
DESCRIPTION OF DEFECT	There are some brake light switches that are not securely fixed due to improper mounting instructions. For this reason, when the brake operation is repeated, the switch may come off the bracket and brake light may remain lit at all times.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-T9HN02	308	2018	21
ABA-T9WHN02			3
TOTAL			24