

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3000	DATE	Mar.17,2020
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : Groupe PSA Japan Co.,Ltd.)		
DESCRIPTION OF DEFECT	On affected vehicles, the tightening torque of the spare wheel support mountings might be non-compliant. Therefore, the mounting nut may be loosened due to vehicle vibration, etc., and the spare tire support may be deformed. In the worst case, the spare tire may fall off and hinder other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-P875G01	PEUGEOT 5008	2019	156
3BA-P875G06			3
		TOTAL	159