

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No..	4692	DATE	March-26-2020
MANUFACTURER	Yano Special Vehicle Co., Ltd.		
DESCRIPTION OF DEFECT	In some fuel tanks , the drain plug is not properly tightened/ attached. Continued use of the tank in such a condition may cause fuel to leak from the drain plug.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-CD5CA	QUON	2019	4
LKG-GK8JWAA	RANGER	2019	1
2KG-FK65FZ	FIGHTER	2019	1
		TOTAL	6