

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	4787	DATE	July 28,2020
MANUFACTURER	NIPPON TREX CO., LTD. 350 Minamiyamashinden, Ina-cho, Toyokawa ctiy, Aichi prefecture, Japan		
DESCRIPTION OF DEFECT	Regarding some of the van type refrigerated/freezer semi-trailers, the strength of joint between the body rail and the side panel is insufficient because of inappropriate construction management. Therefore, there is a possibility that the cracks may occur on said joint due to the burden at the time of running, and the body rail may be peeled off. And in the worst case, it may not be able to continue to run because the body rail will break and it may hit the tire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VFR241HB	—	2018	2
VFR241HD	—	2018	2
VFR241HE	—	2018	1
VFR241HG	—	2019	2
VFR242DN	—	2017	1
VFR242DU	—	2018	4
VFR243AJ	—	2019	1
VFR245BC	—	2018	9
VFR245BD	—	2018	2
VFR245BE	—	2018	2
VFR245BF	—	2019	4
VFR245BG	—	2019	2
VFR341AL	—	2018	1
VFR342BG	—	2018	5
VFR342BK	—	2018~2019	10
VFR342BL	—	2019	3
VFR344AF	—	2016	1
VFR344AH	—	2016	1
VFR344AN	—	2018~2019	5
VFR344AP	—	2018	5
VFR345AZ	—	2018	1
VFR345BA	—	2018	2
VFR345BB	—	2018	1
VFR345BC	—	2018	1
VFR345BE	—	2019	1
VFR345BF	—	2019	1
VFR345BG	—	2019	1
		TOTAL	71