

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3063	DATE	July 28, 2020
MANUFACTURE	DS Automobiles (Japanese Importer : Groupe PSA Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On affected vehicles, coolant water may leak at welded portion of the degassing tank due to insufficient welding. In the worst cases, the leakage may cause illumination of water temperature warning light and engine overheating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-D34HN05	DS 3 Crossback	2019	24
	TOTAL		24