

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4782	DATE	JULY-31-2020
MANUFACTURER	YAMABIKO CORPORATION President & C.E.O. Yoshiaki Nagao		
SUMMARY OF DEFECT	About the agrochemical spraying vehicle of four-wheel steering, the fastening torque of bolt for steering device was reduced. Therefore, due to the applied load of when steering, the fastening bolt may get loose, and in the worse-case scenario, it may not be able to be steered.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDM-S1085A	KIORITZ SPEED SPRAYER SSVH1085FS	2019~2020	152
		TOTAL	152