

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3070	DATE	August 05, 2020
MANUFACTURER	KTM AG  (Japanese Importer : KTM Japan KK)		
DESCRIPTION OF DEFECT	Market monitoring has shown us that fuel may leak and escape out of fuel tank because of improper production process. Unevenness may occur on the sealing surfaces in the area of the fuel pump and fuel level sensor during the vehicle' s life cycle. This may result in leakages.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
701SPUBV47	SVARTPILEN 701	From 2019 to 2020	100 UNITS
2BL-HQV701	VITPILEN 701	From 2018 to 2020	164 UNITS
		TOTAL	264 UNITS