VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	gai-3081	DATE	August 31, 2020	
MANUFACTURER	DUCATI MOTOR HOLDING SpA			
	(Japanese Importer: DUCATI JAPAN Ltd.)			
DESCRIPTION OF DEFECT	detachment of brake especially but not exclu	pad friction mate sively when used i e vehicle front bra	ootential issues involving rial from the back plate, in a corrosive environment. ake performance could be like pads equipment.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-HC00	1299 SUPERLEGGERA	2017	23
		TOTAL	23