

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~(~~ Import Vehicles)

CAMPAIGN No.	Gai-3103	DATE	2020/10/1
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain A-Class vehicles (177 platform) the toe-in of the front axle might be adjusted incorrectly. In this condition, no impact to driving characteristics and ESP operation exists, however, rolling resistance might be increased. This would lead to an increase of CO2 emissions. In this case, the vehicles might not meet the certified condition.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4BA-177051M	Mercedes-AMG A35 4MATIC	2020	9
		TOTAL	9