Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai- 3113	Date	Oct. 23, 2020		
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)				
Description of defect	A concern has been identified with certain Jaguar XJ 2010 to 2013MY vehicles and 2016 to 2019MY vehicles where, when connected to Jaguar Land Rover's Symptom Driven Diagnostics (SDD) device and an update to the Restraint Control Module (RCM) is unsuccessfully undertaken, the calibration may default to a pre-set condition. In the event of a frontal impact of a sufficient severity to require the Supplementary Restraint System (SRS) to deploy the front airbags, the airbags will deploy but at impact thresholds that exceed those which provide the required occupant protection. Failure of the airbags to deploy as required can lead to increased injuries to the occupants.				

Туре	Commercial name	Model year recalled		Number of vehicles
CBA-J12LA	「XJ Lux.」 「XJ Prem. Lux.」	2010-2011		4
CBA-J128B	「XJ Lux.」 「XJ Prem. Lux.」	2015-2018		2
			Total	6