

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3115	DATE	October 30, 2020
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : Groupe PSA Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On affected vehicles, the engine cooling circuit degassing pipe was incorrectly fitted to vehicle and contacts with radiator inlet pipe. As this consequence, water leak may happen due to the wear of radiator inlet pipe. In the worst case, engine overheat occurs.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-P875G06	5008	2018-2019	99
	TOTAL		99