VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-3116	DATE	October 30, 2020
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer :	Groupe PSA Japan Co., L	td.)
DESCRIPTION OF DEFECT	There is the risk of insufficient battery charging due to improper ECU program on alternator output voltage after driving over 60,000km. This may cause difficult-to-start and battery waring lamp turning on, in the worst case, may lead no operation of ABS.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-A9HM01	208	2015-2016	151
ABA-A9CHM01	208	2015	80
	TOTAL		231