

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3123	DATE	2020/11/05
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain A- Class (177 platform) vehicles, the four locknuts securing the airbag might be missing. In case of a crash with deployment of the airbag, the airbag module might separate from the base plate and enter the passenger compartment with high velocity. Thus, the restraint effect of the driver airbag might be impaired, and the risk of injury for the occupants could be increased.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-177084	A180	2019	3
3DA-177012	A200d	2020	1
		TOTAL	4