

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-3143	DATE	22/December/2020
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	Volvo Cars have identified an issue with the driver airbag. In the event of a crash with a driver airbag activation, the propellant inside the driver airbag may rupture.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[S80]	2001-2003	525
VOLVO	[S60]	2001-2003	2,182
TOTAL			2,707