

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	GAI-3148	DATE	Dec.24,2020
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	On some cranes, the electric devices are equipped with a 12V relay as opposed to the regular 24V relay. Therefore, if the relay is used as is, the relay may malfunction, and it might not be possible to turn the headlights on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
FAUN	「ATF220G-5」	2019	2
FAUN	「ATF400G-6」	2020	1
		TOTAL	3