VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3152	DATE	21, Jan, 2021	
MANIJEACTUDED	Automobili Lamborghini SpA			
MANUFACTURER	(Japanese Importer: Audi Japan KK)			
	On some of the affected vehicles, the integrity of the quick connector of the fuel			
	line located in the engine compartment may be compromised. In rare instances high			
DESCRIPTION	engine compartment temperatures subject the quick connectors to temperatures			
OF DEFECT	above the design operating specification limit.			
	These elevated temperatures ca	n lead to the quick connect material softening which		
	could potentially result in a fue	el leak.		

ТҮРЕ	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ABA-ZLDHU	URUS	2019 - 2020	678