

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3185	DATE	March 4, 2021
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : Groupe PSA Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On affected vehicles, dashboard harness may cut due to contact with steering column. This may cause no operation of either horn, windscreen wiper, Advance Driver Assistance System, driver airbag or turn signals.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-R85G06	508	2018 - 2020	788
3DA-R8AH01	508	2018 - 2020	940
TOTAL			1,728