

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4908	DATE	Mar 19, 2021
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	Some of the displays of vehicles equipped with the optional emergency braking device are not waterproofed due to improper manufacturing instructions for the LCD panel mounting part. Therefore, if rainwater or the like invades from the mounting portion and continues to be used as it is, the control board inside the display may be corroded and damaged, and the engine rotation may be restricted by fail-safe, resulting in inoperability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-1TZ3	「TZ704」	2019 - 2020	86
YDN-1R7	「R2-4」	2019 - 2020	27
TOTAL			113