VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4915		DATE	March 22, 2021
MANUFACTURER	ISEKI & CO., LTD.			
DESCRIPTION OF DEFECT	Inappropriate clutch control program in the transmision system of agriculutural tractor may cause the clutch to be worn out drastically especially when it starts towing heavy weights, which has risks to make vehicle disabled at worst.			
ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
YDR-T262F	TJW1233	2018~2021		276
YDR-T262F	MF4512J	2019~2021		13
YDR-T263F	TJW1153	2019~2021		73
YDR-T263F	MF4511J	2020		1
YDR-T270F	TJW1303	2020~2021		22
			TOTAL	385