

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4944	DATE	May 7, 2021	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	With regards to the Instrument cluster meter for heavy duty trucks, due to the inappropriate after market software setting, the AEBS (Advanced Emergency Braking System) warning display and buzzer may not activate.			
COMMERCIAL NAME	TYPE	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CD4BA	Quon	2020	1	
2PG-CD5AL	Quon	2018	1	
2PG-CD5BA	Quon	2018 - 2020	12	
2PG-CD5BL	Quon	2017 - 2020	6	
2PG-CD5CA	Quon	2017 - 2020	121	
2PG-CD5CE	Quon	2018 - 2020	35	
2PG-CD5CL	Quon	2017 - 2020	13	
2PG-CG4CA	Quon	2020	3	
2PG-CG5CA	Quon	2017 - 2020	208	
2PG-CG5CE	Quon	2018 - 2020	17	
2PG-CG5CL	Quon	2017 - 2019	4	
2PG-CW4AL	Quon	2020	1	
2PG-CW5AL	Quon	2017 - 2020	50	
2PG-CW5BL 2PG-CW5BLKai	Quon	2018 - 2020	9	
2PG-CW5CA	Quon	2018 - 2020	11	
2PG-CW5CL 2PG-CW5CLKai	Quon	2017 - 2020	13	
2PG-CX5BA	Quon	2017 - 2020	10	
2PG-CX5BL	Quon	2017 - 2020	8	
2PG-GK5AAB	Quon	2017 - 2020	105	
2PG-GK5AAD 2PG-GK5AADKai	Quon	2017 - 2020	46	
2PG-GK5AAE 2PG-GK5AAEKai	Quon	2018 - 2020	11	
2PG-GK5AAK	Quon	2019	1	
		TOTAL	686	