VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3225	DATE	2021/6/3	
MANUFACTURE	Mercedes-Benz AG			
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)			
DESCRIPTION OF DEFECT	On certain GLB vehicles (247 platform) the side spoilers at the tailgate might not have been mounted according to specifications. In this case, it cannot be excluded that a side spoiler detaches from the vehicle during driving. This would increase the risk of a crash or injury for other road users.			
	This would increase the risk of a	i crash or injury for other road u	sers.	

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
3DA-247612M	GLB200d	2020	88
5BA-247647M	GLB250 4MATIC		28
		TOTAL	116