

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3226	DATE	2021/6/3
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	<p>On certain vehicles of E-Class (213 platform) and AMG GT 4-doors Coupe (290 platform) with AMG Gasoline-engine and 4MATIC the screw connection of the power supply on the starter might not have been installed according to specifications.</p> <p>In case of an incorrect screw connection, the wire of the power supply of the starter might come into contact with the starter housing. Over time this could lead to a wear through the wire insulation of the power supply due to relative movements which could result in a short circuit.</p> <p>Depending on the kind of short circuit, a stalling of the vehicle and a risk of fire cannot fully be excluded.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-213088	Mercedes-AMG E63 4MATIC+	2018	2
CBA-213089	Mercedes-AMG E63S 4MATIC+		7
		2019	4
		2020	1
7BA-213089		2021	1
CBA-213289	Mercedes-AMG E63S 4MATIC+ Wagon	2018	1
		2020	2
4BA-290689	Mercedes-AMG GT63S 4MATIC+	2019	48
		2020	10
		2021	4
		TOTAL	80