

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~(~~ Import Vehicles)

CAMPAIGN No.	Gai-3227	DATE	2021/6/3
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain GLB vehicles (247 platform) the wheel arch covers on the front fenders might not have been mounted according to specifications. In this case, it cannot be excluded that a wheel arch cover detaches completely from the vehicle during driving. This would increase the risk of a crash or injury for other road users.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-247612M	GLB200d	2020	47
		TOTAL	47