

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3229	DATE	June 16, 2021
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	Due to a manufacturing process errors, dash panels may have been produced with an insufficient or missing passenger airbag score-line. In a crash with passenger airbag activation, the airbag may not open and inflate fully, and in the worst case, the passengers may be injured excessively.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-F2DJPA	Audi RS7 SB Air- suspension	2021	1
3AA-F2DJPL	Audi RS6 Avant Air- suspension	2021	2
3AA-F2DJPS	Audi RS7 SB	2021	3
3AA-F2DKMA	Audi S7 SB	2021	1
3AA-F2DKML	Audi S6	2021	1
3AA-F2DKNF	Audi A6 45Tq	2020-2021	21
3AA-F2DKNS	Audi A7 SB 45Tq	2020	12
3AA-F2DLZF	Audi A6 55Tq	2021	1
3AA-F2DLZS	Audi A7 SB 55Tq	2021	2
3CA-F2DFBF	Audi A6 40TDIq	2021	1
3CA-F2DFBS	Audi A7 SB 40TDIq	2020-2021	4
AAA-F2DLZF	Audi A6 55Tq	2019-2020	62
AAA-F2DLZS	Audi A7 SB 55Tq	2019-2020	348
		Total	459