

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|--|------|-------------|
| CAMPAIGN No. | 4979 | DATE | Jun.22 2021 |
| MUNUFACTURER | Mitsubishi Fuso Truck and Bus Corporation | | |
| DESCRIPTION OF DEFECT | Regarding heavy-duty truck and bus engines, due to the variations in manufacturing of oil pumps, some pumps may have a slanted gear shaft. This may cause early wear of gear teeth surfaces. Continued use of the vehicle may cause breakage of gears and a drop in the supply oil pressure to the engine. In the worst case, the vehicle will become unable to operate due to engine seizure, or a fire will occur. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-------------|--------------------|---------------------|-------------------|
| LDG-FU50VY | 「FUSO SUPER GREAT」 | 2010~2011 | 8 |
| LDG-FV50VJR | | 2010~2012 | 282 |
| LDG-FV50VX | | 2010~2012 | 600 |
| LDG-FV50VY | | 2010~2012 | 202 |
| LDG-FV50VZ | | 2010~2012 | 45 |
| LKG-FP54VDR | | 2010~2012 | 1,115 |
| LKG-FP54VER | | 2010~2012 | 186 |
| LKG-FP54VGR | | 2010~2012 | 61 |
| LKG-FS50VZ | | 2010~2012 | 133 |
| LKG-FS54VY | | 2010~2012 | 100 |
| LKG-FS54VZ | | 2010~2012 | 2,282 |
| LKG-FS55VY | | 2010~2011 | 218 |
| LKG-FS55VZ | | 2010~2012 | 554 |
| LKG-FU50VY | | 2010~2012 | 163 |
| LKG-FU54VY | | 2010~2012 | 105 |
| LKG-FU54VZ | | 2010~2012 | 2,170 |
| LKG-FU55VZ | | 2010~2012 | 230 |
| LKG-FV50VX | | 2011~2012 | 140 |
| LKG-FV50VY | | 2010~2012 | 107 |
| LKG-FV50VZ | | 2010~2012 | 329 |
| LKG-FV54VZ | | 2010~2012 | 170 |
| LKG-FY50VY | | 2010~2012 | 75 |
| LKG-FY54VY | | 2010~2012 | 161 |
| QDG-FU50VY | | 2012~2012 | 8 |
| QDG-FV50VJR | | 2011~2014 | 359 |
| QDG-FV50VX | | 2010~2012 | 141 |
| QDG-FV50VY | | 2010~2012 | 159 |
| QDG-FV50VZ | | 2011~2012 | 10 |
| QKG-FP54VDR | | 2010~2014 | 629 |
| QKG-FP54VER | | 2011~2013 | 97 |
| QKG-FP54VGR | | 2010~2012 | 51 |
| QKG-FS50VZ | 2011~2012 | 130 | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|--------------------|---------------------|-------------------|
| QKG-FS54VY | 「FUSO SUPER GREAT」 | 2011～2013 | 38 |
| QKG-FS54VZ | | 2011～2014 | 1,407 |
| QKG-FS55VY | | 2012～2013 | 50 |
| QKG-FS55VZ | | 2011～2013 | 291 |
| QKG-FU50VY | | 2010～2012 | 81 |
| QKG-FU54VY | | 2011～2012 | 56 |
| QKG-FU54VZ | | 2011～2014 | 1,219 |
| QKG-FU55VZ | | 2011～2013 | 117 |
| QKG-FV50VX | | 2011～2014 | 849 |
| QKG-FV50VY | | 2011～2012 | 131 |
| QKG-FV50VZ | | 2011～2012 | 212 |
| QKG-FV54VZ | | 2011～2012 | 93 |
| QKG-FY50VY | | 2011～2012 | 45 |
| QKG-FY54VY | | 2012～2012 | 81 |
| LKG-MS96VP | | 「FUSO AERO ACE」 | 2010～2012 |
| | 「FUSO AERO QUEEN」 | 2010～2012 | 78 |
| QRG-MS96VP | 「FUSO AERO ACE」 | 2012～2015 | 416 |
| | 「FUSO AERO QUEEN」 | 2012～2013 | 34 |
| LKG-AS96VP | 「SPACEARROW A」 | 2010～2011 | 12 |
| | 「SPACEWING A」 | 2010～2011 | 5 |
| TOTAL | | | 16,719 |