

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4984	DATE	JUN-28-2021
MANUFACTURER	YAMABIKO CORPORATION President & C.E.O. Hiroshi Kubo		
SUMMARY OF DEFECT	Due to the incorrect shape of the shift lever in the transmission of the agricultural chemical spraying vehicle, it may be damaged after repeated shifts. Therefore, there is a risk that the gear cannot be changed and the vehicle cannot be started.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDM-S1085A	KIORITZ SPEED SPRAYER SSVH1085FS	2019~2021	235
		TOTAL	235