VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles CAMPAIGN No. Gai-3244 DATE 2021/7/8 MANUFACTURE MercedeShooting Brakeenz AG (Japanese Importer : MercedeShooting Brakeenz Japan Co,. Ltd.) **DESCRIPTION OF** On certain CLA (117 platform), GLA (156 platform), A-Class (176 platform) and B-Class (242, DEFECT 246 platform) vehicles a bore in the universal joint on the steering shaft might not meet specifications. In this case, a play between the bearing in the bore hole and the universal joint might occur. Over time, this play could increase and lead to noises and an imprecise steering feel. If the symptoms are not recognized over a longer period, the bearing could separate from the universal joint. In this case, the steerability of the vehicle would be impaired, which could increase the risk of a crash.

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
DBA-176042	A180	2017	808
		2018	6
DBA-176051	A250 4MATIC	2017	52
		2018	5
CBA-176052	Mercedes-AMG A45 4MATIC	2017	105
		2018	14
DBA-156942	GLA180	2017	187
		2018	68
DBA-156947	GLA220 4MATIC		328
DBA-156946	GLA250 4MATIC	2017	34
CBA-156952	Mercedes-AMG GLA45 4MATIC	2018	51
DBA-117342	CLA180	2017	287
		2018	1
DBA-117942	CLA180 Shooting Brake	2017	285
DBA-117347	CLA220 4MATIC	2018	3
DBA-117947	CLA220 4MATIC Shooting Brake		4
DBA-117351	CLA250 4MATIC	2017	53
DBA-117951	CLA250 4MATIC Shooting Brake		36

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
DBA-117951	CLA250 4MATIC Shooting Brake	2018	1
CBA-117352	Mercedes-AMG CLA45 4MATIC	2017	47
CBA-117952	Mercedes-AMG CLA45 4MATIC		39
GDA-117952	Shooting Brake	2018	1
DBA-246242	B180	2017	610
DDA-240242		2018	42
DBA-246247	B220 4MATIC		7
DBA-246246	B250 4MATIC	2017	16
		TOTAL	3,090