

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	gai-3251	DATE	July 20, 2021
MANUFACTURER	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	The engine control unit (ECU) of vehicles may incorrectly detect an ECU abnormality, due to inappropriate control program setting of abnormality judgement when the accelerator pedal is operated during acceleration/deceleration or when the gear shift positions are changed in the manual mode. Because of that, if keeping on driving as it is, the engine warning light would turn on and the engine control system would move to the failsafe mode, and then, the engine performance may limit.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-BBM5P	MEGANE R.S.	2018-2020	724
		TOTAL	724