

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3255	DATE	July 20 <sup>th</sup> , 2021
MANUFACTURER	BMW ALPINA (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	<p>There have been indications that this type of gas generator can leak in the long term. This leak enables the propellant in the gas generator to absorb moisture. A high moisture absorption and re-drying over longer periods of time can lead to a breakdown of the propellant.</p> <p>In this case, in the event of an accidental airbag deployment, a very high internal pressure in the gas generator can occur and in the worst case it can burst the gas generator and metal parts can cause possibly injuries.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GF-3E44	B3 3.3	1999-2000	95
	B3 3.3 Coupe	2000	16
		TOTAL	111

This recall will be notified again to adjust the recall GAI-2975, which was submitted on 22. January 2021. The adjustment is based on the results of further analyses.