

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

|                       |   |      |                 |
|-----------------------|---|------|-----------------|
| CAMPAIGN No.          | Gai-3259  | DATE | August 17, 2021 |
| MANUFACTURE           | Royal Enfield (A unit of Eicher Motors Ltd.)<br>(Japanese Importer : PCI.co.Ltd)  |      |                 |
| DESCRIPTION OF DEFECT | Brake calipers may be corroded by salt for melting snow. The corrosion of the brake calipers can cause the brakes to drag or braking performance could be affected or become ineffective. |      |                 |

| TYPE    | COMMERCIAL NAME     | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------|---------------------|---------------------|-------------------|
| CNEG    | 「Continental GT650」 | 2019                | 1                 |
| ME3EGP1 | 「Continental GT650」 | 2020                | 40                |
| ME3EHP1 | 「INT650」            | 2020                | 56                |
|         | TOTAL               |                     | 97                |