

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	外 - 3266	DATE	Sept 10 2021
MANUFACTURE	LIEBHERR (Japanese Importer : Liebherr-Japan Co.,LTD.)		
DESCRIPTION OF DEFECT	The maximum driving speed setting does not comply for Japanese safety regulation for road and vehicles, and it is possible to change it by someone. Under driving speed faster than 50km/h, tire specification on 1 st axle is not strong enough for actual axle load and if a car continue to drive faster than 50km/h, tires may be flat and not be able to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	LTM1075NX	2020~2021	4 units
		TOTAL	4 units