

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3282	DATE	27 September, 2021
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	The affected vehicles may have been fitted with a starter on which the threaded joint for the end cover can come loose and this can cause the starter to fail. As a result, the vehicle might not start..		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-E3K29	Cayenne S	2019	17
ABA-E3K29A	Cayenne S	2019	58
ABA-E3K30	Cayenne	2019	14
ABA-E3K30A	Cayenne	2019	39
ABA-E3K40A	Cayenne Turbo	2019	40
		Total	168