

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-3283	Date	Sep. 28, 2021
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	The car equipped with the Ingenium I6 3.0L petrol engine, where the electric supercharger experiences intermittent failure. Should the electric supercharger fail to operate, the vehicle will experience reduced performance and may not meet the On-Board Diagnostics (OBD) malfunction detection requirements of regulations in Japan. Replacing the electric supercharger.		

Type	Commercial name	Model year recalled	Number of vehicles
7AA-LW3UD	Range Rover Sport	2021	1
Total			1

(JIS A4 size)