

**Form No. 4: Summary of Recall Campaign in English (Related to Article 2)**

**Vehicle Safety/Pollution Recall Campaign in Japan**

Import Vehicles

Campaign No.	Gai-3285	Date	Sep. 28, 2021
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	Front row seat track end stop bracket may become deformed. Deformed front row seat track end stop brackets may allow the front row seat to latch further forward than intended by design. Vehicles with deformed end stop brackets could, in the event of a crash, allow reduced seat strength and seat performance integrity, increasing the risk of injury.  Replacing the seat track.		

Type	Commercial name	Model year recalled	Number of vehicles
3BA-LE62XAA	DEFENDER 90	2021	25
3BA-LE62XCA			150
		Total	175

(JIS A4 size)