VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

 CAMPAIGN No.
 Gai-xxx2
 DATE
 2021/9/29

 MANUFACTURE
 Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)
)

 DESCRIPTION OF DEFECT
 On certain S-Class vehicles (223 platform) the bolting of an electrical wiring on the pre-fuse box in the passenger-side footwell might not meet specifications. In this case, the electric resistance of the connection might increase. In combination with the high electrical currents potentially flowing through this connection, the temperature in this area might increase. As a consequence, the risk of fire cannot be ruled out completely.

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
5AA-223163	S500 4MATIC	2021	10
		TOTAL	10