

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3298	DATE	Sep 30 2021
MANUFACTURE	FCA Italy S.p.A. (Japanese Importer : Fiat Chrysler Automobiles Japan Ltd.)		
DESCRIPTION OF DEFECT	The headlight washer fluid tubes may disconnect from the fittings with consequent leakage of liquid. It is therefore necessary to apply clamps on the headlight washer tube fittings to ensure a tight seal.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-31214T	「595」	2021	480
	「595C」	2021	74
		TOTAL	554