

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3302	DATE	18 th October 2021
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	During the cell module production process for the high voltage battery, impurities in the cells could not have been completely avoided. These impurities can trigger a short circuit in the high voltage battery. In the worst case, this short circuit can lead to a thermal incident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-5X20	BMW 330e	2020	4
3LA-JA20PH	BMW 530e iPerformance	2020	31
3LA-7D30	BMW 745e	2020	8
3LA-7W30	BMW 745Le xDrive	2020	1
3LA-TS20	BMW X3 xDrive30e	2020	61
3LA-TA30	BMW X5 xDrive45e	2020	39
3LA-YU15T	MINI Cooper SE Crossover A4	2020	32
3LA-22BS15	MINI Cooper SE Crossover A4	2020	23
		TOTAL	199