VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3308	DATE	2021/10/28		
MANUFACTURE	Mercedes-Benz AG				
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)				
DESCRIPTION OF DEFECT	(Japanese Importer: Mercedes-Benz Japan Co,. Ltd.) On certain EQC vehicles (293 platform) the wiring harness of the electrical steering might have been damaged during the assembly process. In this case, water might ingress into the wiring harness through a damaged isolation and advance over time into the steering control unit. As a consequence, the steering assist might fail spontaneously, also during driving. This would increase the risk of a crash. In this case, the driver would be notified by a red warning message in the instrument cluster.				

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ZAA-293890	EQC400 4MATIC	2021	268
		TOTAL	268