

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5052	DATE	OCT-11-2021
MANUFACTURER	YAMABIKO CORPORATION President & C.E.O. Hiroshi Kubo		
SUMMARY OF DEFECT	Due to improper design of the parking brake of the agricultural chemical spraying vehicle, the hook and gear may not mesh with each other and the hook may then become deformed. If the vehicle is used as is, with the hook deformed, the parking brake may be released and the vehicle could roll unexpectedly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
S6053A	KIORITZ SPEED SPRAYER SSV6053FS	2017~2021	181
		TOTAL	181