

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-3301	DATE	16/November/2021
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	If the capless fuel filler insert has been damaged, the fuel filler insert may, in some rare occasions, not withstand water i.e., heavy rain. If this happens there is a risk that the fuel tank may be contaminated with water. It is not possible to visually notice if the capless insert is damaged.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[V40]	2016-2019	11,551
VOLVO	[V40 Cross Country]	2016-2019	3,794
		TOTAL	15,345