VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5061	DATE	November. 18. 2021		
MANUFACTURER	HONDA MOTOR CO., LTD.				
DESCRIPTION OF DEFECT	Headlights or front fog lights may have been subjected to inadequate optical axis inspection control at the vehicle manufacturing plant; therefore, the optical axis of such headlights or front fog lights may not be in compliance with the Safety Regulations for Road Vehicles.				

TYPE	COMMERCIAL	MODEL YEAR		NUMBER OF
	NAME	RECALLED		VEHICLE
DBA-JF3	「N-BOX Custom」	2019		1
6BA-JF3	IN-DOX Custom	2021		4
6BA-JG3	「N-ONE」	2021		3
6BA-JG4	'N-ONE]	2021		1
6AA-RV5	「VEZEL」	2021		1
6BA-GR5	「FIT」	2020		1
6AA-GP7	「SHUTTLE」	2019		1
			TOTAL	12